

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2024

Submitted Date:

06/07/2024

Document Number:

701104010

**FIELD INSPECTION FORM**Loc ID 314214 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Welsh, Brian		brian.welsh@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273473	WELL	PR	10/18/2004	GW	099-06879	STATE 1-14	EG

**General Comment:**

Flowline integrity inspection

**Location**Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	no labels on barrels.		
Corrective Action:	Comply with Rule 605.h.(3)	Date:	06/22/2024
Type	WELLHEAD		
Comment:	No well head sign Comply with Rule 605.d.(1)		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused tubing on location. Junk around compressor. Unused flowlines in fenced area. Open ended unsed lines with OOSLAT.		
Corrective Action:	OOSLAT unused lines imediately until lines are removed. Remove unused flowlines. Remove unused junk from location. Comply with Rule 606	Date:	07/31/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
Comment:	Tipped over barrel with spilled fluids at the compressor. Operator was notified by email May 31, 2024 with photos included.			
Corrective Action:	Report and clean up spill Comply with Rule 912			Date: 06/10/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	273473	Type:	WELL	API Number:	099-06879	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	Barrels without secondary containment

Comment: Barrels without secondary containment

Corrective Action: Store barrels in secondary containment.

Date: 06/22/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104011	Flowline integrity inspection 701104010 photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578136">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578136</a>