

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Jun 6, 2024 at 2:57:59 PM
CO

Photo # 93 From entrance to location



Jun 6, 2024 at 3:03:35 PM
CO

Photo # 94 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 95 Location



Photo # 96 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Jun 6, 2024 at 2:58:35 PM
CO

Photo # 97 Location



Jun 6, 2024 at 2:58:58 PM
CO

Photo # 98 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 99 Location



Photo # 100 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 101 Location



Photo # 102 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 103 Unmarked deadman



Photo # 104 Same unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 105 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 106 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 107 Wellhead sign weathered & cracking/starting to become illegible



Photo # 108 Wellhead sign weathered & cracking/starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FOSSIL CREEK RWF 33-6 Pad

Location ID: 334999



Photo # 109 Wellhead sign weathered & cracking/starting to become illegible