

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2024

Submitted Date:

05/31/2024

Document Number:

714201080

FIELD INSPECTION FORMLoc ID 327796 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| , | | ECMCInspections@Oxy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 247364 | WELL | TA | 03/14/2017 | OW | 123-15161 | FRANK H21-15 | TA |

General Comment:

THIS IS A WELLHEAD INSPECTION.

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | debris in/outside of wellhead fencing. See attached photos. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 06/14/2024 |

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | iron | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 247364

Type: WELL

API Number: 123-15161

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/19/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 1

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| <div>ECMC Inspection Report Summary</div> <div>WEATHER CONDITIONS: cloudy, dry ground</div> <div>On Friday, May 31, 2024 at approximately 1200, I, Inspector Brittani Santistevan, conducted an on-site inspection at FRANK H21-15 (Kerr McGee Oil & Gas Onshore), at location ID: 327796 in WELD COUNTY, Colorado.</div> <div>While there, I observed a TA wellhead.</div> <div>During this inspection the following possible compliance issues were observed:</div> <div>1. It appears to be debris inside/outside of wellhead fencing. Comply with Rule 606. (Corrective Actions Date: June 14, 2024) See attached photo #2.</div> <div>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</div> <div>This is a summary of inspection report.</div> | santistb | 05/31/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403810920 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571627 |
| 714201081 | Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571624 |