

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/10/2024

Submitted Date:

06/10/2024

Document Number:

714201120

FIELD INSPECTION FORM

Loc ID 332306 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271733	WELL	SI	03/01/2024	OW	123-22118	BROWN 2-6	TA
422506	WELL	SI	07/01/2021	GW	123-33288	LEE 21-6	TA
422515	WELL	SI	07/01/2021	OW	123-33293	LEE 7-6	TA
422518	WELL	SI	07/01/2021	OW	123-33296	LEE 28-6	TA

General Comment:

[THIS IS A FOLLOW UP INSPECTION.](#)

Inspected Facilities

Facility ID: 271733 Type: WELL API Number: 123-22118 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PREVIOUS INSPECTION

Comment: TA

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422506 Type: WELL API Number: 123-33288 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PREVIOUS INSPECTION

Comment: TA

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422515 Type: WELL API Number: 123-33293 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PREVIOUS INSPECTION

Comment: TA

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422518 Type: WELL API Number: 123-33296 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PREVIOUS INSPECTION

Comment: TA

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/17/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: None

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714201045 AND IN REPOSE TO FIRR DOC#:403814604 . It appears all previous corrective actions assigned to this location have been resolved. For additional information please refer to previous inspection DOC#:714201045 or FIRR DOC#: 403814604	santistb	06/10/2024