

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/10/2024

Submitted Date:

06/10/2024

Document Number:

715500177

**FIELD INSPECTION FORM**

Loc ID 335724 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
, TEP	(970) 285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435606	WELL	SI	09/01/2023	GW	103-12078	FEDERAL RGU 333-24-198	PA

**General Comment:**

[ECMC Inspection Report Summary](#)

On Monday, 06/10/2024, Inspector Kirby Burchett, was on location to cut off casing, remove wellhead and install marker following Plug and Abandon operations at TEP Rocky Mountain LLC on the Federal RGU 333-24-198 well, Location #335724, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District, Wildlife Management Plan and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Excavate around wellhead. Cut windows in surface casing. Cut off production casing. Cut off wellhead from surface casing 4' below ground level. Surface and Production casing full of cement. Production casing 16" below cut off surface casing. Weld on dry hole plate. Back fill excavation area.

No follow up inspection is required.

**Inspected Facilities**

Facility ID: 435606 Type: WELL API Number: 103-12078 Status: SI Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500178	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6581352">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6581352</a>