

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/10/2024

Submitted Date:

06/11/2024

Document Number:

705000714

FIELD INSPECTION FORM

Loc ID 320209 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 1125 17TH STREET SUITE 550
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		Regulatory@verdadoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203063	WELL	PR	10/01/2015	GW	001-08469	PETE ROCK 1	PA
320209	LOCATION	AC			-	GREAT WESTERN PETE ROCK 1	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 203063 Type: WELL API Number: 001-08469 Status: PR Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 320209 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403811389 received on 06/03/2024: Impacted soil was discovered while decommissioning the facility. The well has been P&A'd. This historic spill was not ongoing and is contained in the soil.	maclarej	06/11/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000716	Facility decom; Equipment flowlines removed	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582621
705000717	View of location; to West	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582622