

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2024

Submitted Date:

06/05/2024

Document Number:

696306394

FIELD INSPECTION FORMLoc ID 452871 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10661

Name of Operator: CIVITAS NORTH LLC

Address: 555 17TH STREET #3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452981	WELL	PR	03/01/2020	OW	123-45842	Castor 8-59 19-24-12	PR
452985	WELL	PR	03/17/2020	OW	123-45846	Castor Fed 8-59 19-24-1	PR
452987	WELL	PR	03/17/2020	OW	123-45848	Castor Fed 8-59 19-24-6	PR
452989	WELL	PR	08/01/2023	OW	123-45850	Castor Fed 8-59 19-24-4	PR
452991	WELL	PR	08/01/2023	OW	123-45852	Castor Fed 8-59 19-24-3	PR
452994	WELL	PR	12/01/2023	OW	123-45855	Castor 8-59 19-24-16	PR

General Comment:

This is a Well PAD and Production Facility Inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 24-Hour Emergency Contact Number on Wellhead Signs STILL shows Previous Operator's Contact Number; see photos

Corrective Action: Install sign to comply with Rule 605.d.

Date: 06/21/2024

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 15		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Emission Control Device	# 5		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Instrumentatl Air Unit		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		40.645330,-104.012360
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	750 BBLS				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities								
Facility ID:	452981	Type:	WELL	API Number: 123-45842	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	PR							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	452985	Type:	WELL	API Number: 123-45846	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	PR							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	452987	Type:	WELL	API Number: 123-45848	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	PR							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	452989	Type:	WELL	API Number: 123-45850	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	PR							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	452991	Type:	WELL	API Number: 123-45852	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	PR							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	452994	Type:	WELL	API Number: 123-45855	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	PR							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
ECMC Comments								
Comment	User					Date		
Routine Field Inspection	petrie					06/05/2024		
Attached Documents								
You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:								

Document Num	Description	URL
403815259	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6575477
696306395	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6575476

--