

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2024

Submitted Date:

06/12/2024

Document Number:

698602074

**FIELD INSPECTION FORM**

Loc ID: 303969 Inspector Name: St John, William (Cal) On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

19 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253856	WELL	SI	02/01/2024	GW	125-07734	STONE 34-26	SI

**General Comment:**

Routine inspection.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well lease sign located at wellhead.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Well lease sign posted at gas meter run.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at tank.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information posted on well lease sign, gas meter run well lease sign, and tank sign.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Stock panel fencing around surface equipment at remote gas metering location.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Dehydrator	# 1		corrective date
Comment:	Dehydrator on gas meter run inlet.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Shared Meter Shed at remote Gas Meter Run.		
Corrective Action:			Date:

Type: Deadman # & Marked	# 4	
Comment:	Located (4) marked deadmen.	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Bradenhead plumbed to surface.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. Casing valve open.	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Gas fired motor.	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Remote Gas Meter Run located on Stone 2-26 API 125-07227. Digital Gas Meter Run. Meter Calibration/Test Log dated 8-9-23. Well Inlet Valve open. Gas Outlet Valve closed.	
Corrective Action:		Date:
Type: Dehydrator	# 1	
Comment:	Dehydrator on supply gas line.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.020210,-102.368870
Comment:	Located at well location.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	210 BBL
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 253856 Type: WELL API Number: 125-07734 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve closed.  
  
Electronic Well File reflects last Production/Status reported 4/1/2024 and Well Status as SI. Well reported SI since 2-1-2024. Based on current valve settings at time of inspection the well is SI.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698602102	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6584257">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6584257</a>