

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2024

Submitted Date:

06/13/2024

Document Number:

713400124

**FIELD INSPECTION FORM**Loc ID 335844 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

19 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288287	WELL	PR	04/11/2012	GW	045-13180	CASCADE CREEK 697-16-32	PR
290124	WELL	PR	04/01/2020	GW	045-13997	CASCADE CREEK 697-15-01A	PR
290129	WELL	PR	07/11/2012	GW	045-13992	CASCADE CREEK 697-16-31	PR
290130	WELL	PR	09/17/2009	GW	045-13991	CASCADE CREEK 697-16-07	PR
290131	WELL	PR	09/01/2020	GW	045-13990	CASCADE CREEK 697-16-15A	PR
290133	WELL	PR	09/17/2009	GW	045-13988	CASCADE CREEK 697-15-17B	PR
290134	WELL	PR	04/21/2015	GW	045-13987	CASCADE CREEK 697-15-25	PR
290135	WELL	PR	03/01/2023	GW	045-13986	CASCADE CREEK 697-16-06	PR
290136	WELL	PR	10/18/2018	GW	045-13985	CASCADE CREEK 697-15-09A	PR
290138	WELL	PR	01/01/2008	GW	045-13983	CASCADE CREEK 697-09-64	PR

**General Comment:**

CECMC Inspection Report Summary

On 6/10/2024 at approximately 12:03, Compliance Inspector Dusty Popejoy conducted an on-site inspection at Laramie Energy LLC Cascade Creek 697-16-16 Pad at Location ID #335844 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1) Equipment: Cellar, open entry to wildlife, refer to photos with a CA date of 6/20/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-891-6191 or 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 10		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	To pig launcher		
Corrective Action:		Date:	

Type: Other	# 1	
Comment:	Cellar, open entry to wildlife, refer to photos	
Corrective Action:	Cover all cellars with materials sufficient to prevent wildlife access.	Date: 06/20/2024
Type: VRT	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 10	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 6	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 20	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 11	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	HEATED STEEL AST		,
Comment:	Telemetry on tanks				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		,
Comment:	Telemetry on tanks				
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date: <div></div>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <div></div>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <div></div>

Inspected Facilities						
Facility ID:	288287	Type:	WELL	API Number: 045-13180	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	290124	Type:	WELL	API Number: 045-13997	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	290129	Type:	WELL	API Number: 045-13992	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	290130	Type:	WELL	API Number: 045-13991	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	290131	Type:	WELL	API Number: 045-13990	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	290133	Type:	WELL	API Number: 045-13988	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	290134	Type:	WELL	API Number: 045-13987	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	290135	Type:	WELL	API Number: 045-13986	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

<b>Producing Well</b>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	290136	Type:	WELL	API Number:	045-13985	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	290138	Type:	WELL	API Number:	045-13983	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	

<b>Completion</b>			
Operation:			
Date Flowback:			
Contractor:			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Ditches				
Compaction						
Ditches						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400125	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6585630">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6585630</a>