

Photographic Log - 5/1/2024
Raindance FD Off-Site #20-202HNX



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Looking west from northeast corner of containment.			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Looking south from northeast corner of containment.			

Photographic Log - 5/1/2024
Raindance FD Off-Site #20-202HNX



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Downward view, looking westward.			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Looking south from eastern wall of containment.			

Photographic Log - 5/1/2024
Raindance FD Off-Site #20-202HNX



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Looking west from southeast side of containment.			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Looking west from south wall of containment.			

Photographic Log - 5/1/2024
Raindance FD Off-Site #20-202HNX



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Looking north from south wall of containment.			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Looking north from south wall of containment.			

Photographic Log - 5/1/2024
Raindance FD Off-Site #20-202HNX



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Properly sealed liner seams.			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Looking southwest from northeast corner of containment.			

Photographic Log - 5/1/2024
Raindance FD Off-Site #20-202HNX



Blank.

Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions: Looking south from north wall.				Notes/Conditions:			