

Inspection Photos
Sam Funakoshi A2 Flowline Spill
Spill ID 486562



Photo 1 – Spill area.



Photo 2 - Spill area.



Inspection Photos
Sam Funakoshi A2 Flowline Spill
Spill ID 486562



Photo 3 – Soil excavated from spill area temporarily stored on tarp. Contaminated soil beginning to overtop onto clean soil



Photo 4 - Soil stockpile on liner and bermed.



Inspection Photos
Sam Funakoshi A2 Flowline Spill
Spill ID 486562



Photo 5 – Groundwater observed in open excavation. Impacts remained visible in-situ.



Photo 6 - Groundwater observed in open excavation. Impacts remained visible in-situ.

