

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2024

Submitted Date:

06/14/2024

Document Number:

714201130

**FIELD INSPECTION FORM**

Loc ID 327755 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
12 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427979	WELL	SI	11/01/2023	OW	123-35178	Megan State H16-30D	TA

**General Comment:**  
[THIS IS A FOLLOW UP INSPECTION.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:			Date: _____
Corrective Action:			

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused risers, steps near separator. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	07/14/2024
Type	DEBRIS		
Comment:	Debris in tank battery berm. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	06/26/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment at separator. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	05/07/2024

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 427979 Type: WELL API Number: 123-35178 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 04/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 168 Fluid Type: GAS

End Surf Csg Pressure: 1

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p style="color: blue;">THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200965. It appears 3 out of 4 corrective actions previously assigned to this location have been resolved. The remaining unresolved corrective action has been re-assigned to this location with its original corrective action date. 2 new corrective actions were observed at the time of re-inspection. Review the details below for my findings.</p> <p>ECMC Inspection Report Summary                      WEATHER CONDITIONS: sunny, dry ground.                      On Wednesday, June 12, 2024 at approximately 1130, I, Inspector Brittani Santistevan, conducted an on-site inspection at MEGAN STATE H16-30D PAD (Kerr McGee Oil and Gas Onshore), at location ID: 327755 in WELD COUNTY, Colorado.                      While there, I observed a shut in facility.                      During this inspection the following possible compliance issues were observed:                      1. It appears to be unused equipment near separator. Comply with Rule 606. (Corrective Action Date: May 7, 2024) See attached photo #4.                      2. It appears to be debris re-accumulated in the tank battery berm. Comply with Rule 606. (Corrective Action Date: June 26, 2024) See attached photo #14.                      3. It appears unused risers and steps remain near separator. (LOTO risers if being use for future use or remove them) to Comply with Rule 606. (Corrective Action Date: July 14, 2024) See attached photo #5-12.</p> <p style="color: blue;">A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	06/12/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201138	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587290">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587290</a>