

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2024

Submitted Date:

06/14/2024

Document Number:

694100386

FIELD INSPECTION FORMLoc ID 310932 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chambers, Christopher	214-549-7215	kchambers@omimexpetroleum.com	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	
Fisher, Jeremy	970-854-4733	Jeremy_Fisher@omimexgroup.com	
Heibel, Krystal		krystal.heibel@state.co.us	

General Comment:

This is an environmental inspection for Location ID 310932 Bledsoe Federal 14-20. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location			
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			
Corrective Action:		Date: _____	
Good Housekeeping:			
Type			
Comment:	Statewide unnecessary equipment, weeds, waste, and trash requirements. Unused pipes and other equipment. Door to separator housing was blown down and laying on the ground.		
Corrective Action:	Comply with Rule 606		Date: 06/28/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:		No liquid spills present during inspection.	
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			corrective date
Type:	#		
Comment:	Evidence of gas leak from a valve/vertical pipe was noted during an AVO inspection (primarily audible) while on location.		
Corrective Action:	Comply with Rule 608.e.		Date: 06/21/2024
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Environmental**Spills/Releases:**

Type of Spill: _____	Estimated Spill Volume: _____
Comment: <u>No liquid spills or releases noted while on site.</u>	
Corrective Action: _____	Date: _____
Reportable: _____	GPS: Lat _____ Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____

Water Well Complaint:

		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters:

Sample Location: _____	Comment: _____
------------------------	----------------

ECMC Comments

Comment	User	Date
Evidence of a gas leak was observed while on site. High pitched sound caught the inspector's attention and it was narrowed down to a single vertical pipe releasing gas. No visible fume/plume or odors were detected, however there was a slight breeze at the time which may have hindered the visual and olfactory indicators.	robinsotl	06/14/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100387	photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587645