

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Jun 12, 2024 at 11:22:59 AM  
CO



Jun 12, 2024 at 11:23:36 AM  
CO

TEP Rocky Mountain LLC  
970-285-9377  
JOHNSON PRODUCTION FACILITY  
COC NONE  
API

RWF 11-31	RWF 432-31	05-045-17142	05-045-17118
RWF 12-31	RWF 511-31	05-045-17134	05-045-17135
RWF 21-31	RWF 521-31	05-045-17131	05-045-17128
RWF 32-31	RWF 537-31	05-045-17117	05-045-17003
RWF 23-31	RWF 534-30	05-045-17124	05-045-16185
RWF 31-31	RWF 51-30	05-045-17137	05-045-16199
RWF 312-31	RWF 312-30	05-045-17133	05-045-16199
RWF 31-31	RWF 314-30	05-045-17133	05-045-16199
RWF 321-31	RWF 40-30	05-045-17130	05-045-16205
RWF 302-31	RWF 423-30	05-045-17135	05-045-16199
RWF 302-31	RWF 434-30	05-045-17130	05-045-16199
RWF 331-31	RWF 44-30	05-045-17122	05-045-16204
RWF 303-31	RWF 443-30	05-045-17119	05-045-16199
RWF 411-31	RWF 414-30	05-045-17136	05-045-16202
RWF 415-31	RWF 505-30	05-045-17132	05-045-16199
RWF 421-31	RWF 531-30	05-045-17128	05-045-16199
RWF 422-31	RWF 543-30	05-045-17135	05-045-16189
RWF 431-31	RWF 542-30	05-045-17121	05-045-16199

COC 070819  
NEW SEC 31/T65/RB4W  
GARFIELD COUNTY, CO  
EMS 911  
ACCESS FROM CR. 320

TEP Rocky Mountain LLC  
970-285-9377  
JOHNSON PRODUCTION FACILITY

RWF 12-31	05-045-17134-00
RWF 312-31	05-045-17133-00
RWF 412-31	05-045-17132-00
RWF 21-31	05-045-17131-00
RWF 321-31	05-045-17130-00
RWF 423-31	05-045-17129-00
RWF 521-31	05-045-17128-00
RWF 22-31	05-045-17127-00
RWF 322-31	05-045-17126-00
RWF 202-31	05-045-17125-00
RWF 31-31	05-045-17123-00
RWF 331-31	05-045-17122-00
RWF 231-31	05-045-17121-00
RWF 32-31	05-045-17120-00
RWF 322-31	05-045-17119-00
RWF 322-31	05-045-17118-00
RWF 332-31	05-045-17103-01
RWF 231-31	05-045-17124-00
RWF 231-31	05-045-17124-00

NEW SEC 31/T65/RB4W  
GARFIELD COUNTY, CO  
EMS 911  
ACCESS FROM CR 320

Photo # 530 From entrance to location

Photo # 531 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Jun 12, 2024 at 11:23:21 AM  
CO



Jun 12, 2024 at 11:24:11 AM  
CO

Photo # 532 Location

Photo # 533 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Photo # 534 Location



Photo # 535 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Photo # 536 Location



Photo # 537 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Photo # 538 Location



Photo # 539 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Photo # 540 Location



Photo # 541 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Photo # 542 Unmarked deadman



Photo # 543 Same unmarked deadman

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



**Photo # 544 Stored farm equipment in the interim area & on location**



**Photo # 545 Stored farm equipment on location & stored trailer in the interim area**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Photo # 546 Stored trailer in the interim area



Photo # 547 Stored farm equipment on location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Photo # 548 Stored farm equipment in the interim area



Photo # 549 Stored farm equipment in the interim area

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Photo # 550 Debris



Photo # 551 Stored farm equipment in the interim area

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



**Photo # 552 Rupture disc vent line does not comply with CECMC pressure safety device rules (RWF 533-30 separator)**



**Photo # 553 Rupture disc vent line does not comply with CECMC pressure safety device rules (RWF 533-30 separator)**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



**Photo # 554 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 555 Barbed wire fence needs maintenance/wildlife hazard**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



**Photo # 556 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 557 Barbed wire fence needs maintenance/wildlife hazard**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



**Photo # 558 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 559 Barbed wire fence needs maintenance/wildlife hazard**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



**Photo # 560 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 561 Barbed wire fence needs maintenance/wildlife hazard**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



**Photo # 562 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 563 Barbed wire fence needs maintenance/wildlife hazard**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



**Photo # 564 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 565 Debris**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Photo # 566 Open ended load line



Photo # 567 Open ended load line

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOHNSON RWF 434-30 Pad

Location ID: 335509



Photo # 568 Open ended load line



Photo # 569 Open ended load line