

Inspection Photos

June 12th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 306932

Inspection Document #: 714000824

La Plata County, CO

Township: SESE 30 34N 10W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ute 34-101R
Location ID: 306932

6/12/24
+37.157508,-107.968791
272° W



Photo 1. View of the well pad taken from the access road facing center.

Inspection Photos
Location Name: Ute 34-101R
Location ID: 306932



Photo 2. View of gully erosion that persists in the northern interim reclamation area. Gullies are about 2 feet wide and 2 to 3 feet deep. Current storm water BMPs are not adequate.

Inspection Photos
Location Name: Ute 34-101R
Location ID: 306932



Photo 3. Additional view of gully erosion and sloughing occurring in the northern interim reclamation area. Additional stabilization is needed in this area. Photos taken with a drone from the northern edge facing south.

Inspection Photos
Location Name: Ute 34-101R
Location ID: 306932



6/12/24
+37.157973,-107.968592
278° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Ground view of sloughing occurring in the northern interim reclamation area.

API #: 067-09069

Inspection Photos
Location Name: Ute 34-101R
Location ID: 306932



Photo 5. View of the southern interim reclamation area facing southeast.



Inspection Photos
Location Name: Ute 34-101R
Location ID: 306932

6/12/24
+37.157337,-107.969456
165° S



Photo 6. Reference area comprised of indian rice grass, juniper and gambel oak.

