

Inspection Photos

June 12th, 2024

Operator: Hilcorp Energy Company -10133

Location ID: 333494

Inspection Document #: 714000831

La Plata County, CO

Township: NWSE 32 34N 10W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Argenta 34-10 32-2, 2A
Location ID: 333494



6/12/24
+37.144424,-107.955128
53° NE



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos

Location Name: Argenta 34-10 32-2, 2A

Location ID: 333494



Photo 2. Storm water corrective actions identified in the previous inspection have been addressed/resolved.

Inspection Photos

Location Name: Argenta 34-10 32-2, 2A

Location ID: 333494



Photo 3. View of impacted surface material observed at the pump jacks.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08246, 09383

Inspection Photos

Location Name: Argenta 34-10 32-2, 2A

Location ID: 333494



Photo 4. Tank berm remains damaged, maintenance is needed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08246, 09383