

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/11/2024
Submitted Date:
06/11/2024
Document Number:
699505917

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
319955 _____ MEDINA, JUSTIN _____ 2A Doc Num: _____

Operator Information:
ECMC Operator Number: 28780
Name of Operator: FAHEY OIL & GAS
Address: 93 SOUTH COUNTY ROAD 159
City: STRASBURG State: CO Zip: 80136

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED
Findings:
10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201992	WELL	SI	05/01/2021	GW	001-07396	BULLARD 2 (OWP)	SI

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:					
Type	WELLHEAD				
Comment:	4' barb wire, fence has fallen over				
Corrective Action:					Date:
Type	LOCATION				
Comment:	4' barb wire around all equipment				
Corrective Action:					Date:

Equipment:						corrective date
Type: Gas Meter Run		# 1				
Comment:						
Corrective Action:						Date:
Type: Horizontal Heated Separator		# 1				
Comment:	partially taken apart					
Corrective Action:						Date:
Type: Plunger Lift		# 1				
Comment:						
Corrective Action:						Date:
Type: Bradenhead		# 1				
Comment:	plumbed to surface					
Corrective Action:						Date:
Type: Ancillary equipment		# 1				
Comment:	automation					
Corrective Action:						Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: shares containment with oil tank				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment: spill in containment see pictures					
Corrective Action:					Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 201992 Type: WELL API Number: 001-07396 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>This is an orphan well inspection. At time of inspection the well is in need of MIT, and annual bradenhead test. At time of inspection contaminated soil was observed inside the berm of the tank battery, see pictures . At time of inspection weather conditions were warm, clear, calm.</p>	medinaj	06/11/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505918	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6588729