

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2024

Submitted Date:

06/17/2024

Document Number:

693807344

**FIELD INSPECTION FORM**Loc ID 315502 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Taylor, Chad	(720) 788-6197	chad.taylor@state.co.us	Underground Injection Lead
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Sanford, Anita	970-640-3572	anita.sanford@scoutep.com	Regulatory Specialist
Saint, John		jsaint@scoutep.com	Regional Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230943	WELL	IJ	02/01/2020	ERIW	103-08612	FEE 53AX	AC

**General Comment:**

UIC-5 yr MIT.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	970-675-3700		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	WAG skid		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	230943	Type:	WELL	API Number:	103-08612	Status:	IJ	Insp. Status:	AC
Underground Injection Control									
UIC Violation:		Maximum Injection Pressure:							
UIC Routine									
Inj./Tube:	Pressure or inches of Hg	Previous Test Pressure		MPP		Inj Zone: WEBR			
	(e.g. 30 psig or -30" Hg)								
TC:	Pressure or inches of Hg	Previous Test Pressure		Last MIT:		10/31/2019			
Brhd:	Pressure or inches of Hg	Previous Test Pressure		AnnMTReq:					
Comment:									
Corrective Action:		Date:							
Method of Injection:									
Test Type:	5 Year	Tbg psi:	2072	Csg psi:	1360	BH psi: 0			
Insp. Status:		Pass							
Comment:		UIC-5 yr MIT. Wellhead inspection only. Form 42 Doc#403808130 received 5/30/2024, with test scheduled for 6/13/2024. Test date moved to 6/14/2024 at inspectors request. Pressure well to 1360 psi. Hold for 15 min. Final pressure 1350 psi. -10 psi loss. OK Test witnessed by COGCC using chart on test truck.							
Corrective Action:		Date:							

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807358	Inspection photos 6/14/2024	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6589169">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6589169</a>