

Caerus Piceance LLC  
Piceance Creek Unit F23-18G  
Location ID: 315347



When replaced additional information will be required

Debris

Caerus Piceance LLC  
Piceance Creek Unit F23-18G  
Location ID: 315347



**When replaced additional information will be required**



**Relief vent riser missing rain protection**

Caerus Piceance LLC  
Piceance Creek Unit F23-18G  
Location ID: 315347



**Peeled label and required information missing**



**Missing sign at tank battery**

**Caerus Piceance LLC  
Piceance Creek Unit F23-18G  
Location ID: 315347**



**Location from Northwest corner**



**Location from Southwest corner**

Caerus Piceance LLC  
Piceance Creek Unit F23-18G  
Location ID: 315347



Location from Northeast corner



Location from Southeast corner