

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2024

Submitted Date:

06/11/2024

Document Number:

713601110

FIELD INSPECTION FORM

Loc ID 307701 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|---------------------------|-----------------------------|---------|
| Mattorano, Michael | 575-445-6704/505-652-0416 | mmattorano@wapitienergy.com | |
| Madison, Randy | 575-445-6706/575-420-1120 | rmadison@wapitienergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 89239 | WELL | PR | 09/15/1999 | CBM | 071-06819 | VPR C 7 | RI |

General Comment:

This is a reclamation inspection at the VPR C #7 wellsite.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

| | | | |
|--------------------|---|--|------------------|
| Type | WEEDS | | |
| Comment: | There are noxious weeds along the main access road. Observed Canada thistle, Musk thistle, Houndstongue, Mullein. | | |
| Corrective Action: | Comply with Rule 1003.f. | | Date: 06/18/2024 |

Overall Good: ☐**Spills:**

| | | | | |
|--------------------|--|--------|--|------------------|
| Type | Area | Volume | | |
| Produced Water | WELLHEAD | | | |
| Comment: | There was a dripping water leak coming from the wellhead. | | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. | | | Date: 06/13/2024 |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403821086 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582550 |
| 713601111 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582549 |