

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2024

Submitted Date:

06/11/2024

Document Number:

714201126

**FIELD INSPECTION FORM**

Loc ID 302872	Inspector Name: Santistevan, Brittani	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> ECMC Operator Number: 47120 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Address: P O BOX 173779 City: DENVER State: CO Zip: 80217-				<b>Findings:</b> 33 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159570	WELL	PR	01/18/2016	OW	123-40945	CHEESE 37N-28HZ	PR
159571	WELL	PR	01/26/2016	OW	123-40946	CHEESE STATE 26N-21HZ	PR
159572	WELL	PR	04/01/2019	OW	123-40947	CHEESE STATE 26C-21HZ	PR
159573	WELL	PR	07/01/2018	OW	123-40948	CHEESE STATE 1N-21HZ	PR
159574	WELL	PR	12/31/2015	OW	123-40949	CREAM STATE 28C-21HZ	PR
159575	WELL	PR	01/14/2016	OW	123-40950	CHEESE 16N-28HZ	PR
159576	WELL	SI	02/01/2023	OW	123-40951	CREAM 15N-A28HZ	SI
159580	WELL	PR	01/18/2016	OW	123-40955	CHEESE STATE 27N-21HZ	PR
159581	WELL	PR	01/26/2016	OW	123-40956	CHEESE 38N-28HZ	PR
159582	WELL	PR	01/18/2016	OW	123-40957	CHEESE 38C-28HZ	PR
159583	WELL	PR	12/29/2015	OW	123-40958	CREAM STATE 2N-21HZ	PR
159584	WELL	PR	12/28/2015	OW	123-40959	CREAM 15C-28HZ	PR
159585	WELL	PR	01/18/2016	OW	123-40960	CREAM 36N-28HZ	PR
159587	WELL	PR	06/01/2021	OW	123-40962	CREAM STATE 28N-21HZ	PR
159588	WELL	PR	12/31/2015	OW	123-40963	CREAM STATE 2C-21HZ	PR
159589	WELL	PR	12/25/2015	OW	123-40964	CREAM 37N-28HZ	PR
159590	WELL	PR	11/01/2018	OW	123-40965	CREAM 15N-B28HZ	PR
301326	WELL	SI	07/01/2021	OW	123-29959	MOSER H 28-27	TA

**General Comment:**

THIS IS A WELLHEAD/BATTERY INSPECTION.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris at some wellheads. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	06/25/2024

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 18		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: 159570	Type: WELL	API Number: 123-40945	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; it appears the valves are in an open position.			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 02/16/2023		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 0      Fluid Type: None	
End Surf Csg Pressure: --			
Comment: SUBMIT REPORTS			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 159571	Type: WELL	API Number: 123-40946	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; it appears the valves are in an open position.			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 02/15/2023		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 1      Fluid Type: None	
End Surf Csg Pressure: --			
Comment: SUBMIT REPORTS			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 159572	Type: WELL	API Number: 123-40947	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; it appears the valves are in an open position.			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 12/19/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 1      Fluid Type: NONE	
End Surf Csg Pressure: 0			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 159573	Type: WELL	API Number: 123-40948	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; it appears the valves are in an open position.			
Corrective Action:		Date:	

**BradenHead**

Date of Last Brhd Test: 02/16/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159574 Type: WELL API Number: 123-40949 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159575 Type: WELL API Number: 123-40950 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/16/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159576 Type: WELL API Number: 123-40951 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI; it appears the valves are in a closed position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159580 Type: WELL API Number: 123-40955 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/16/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159581 Type: WELL API Number: 123-40956 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/16/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159582 Type: WELL API Number: 123-40957 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/15/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159583 Type: WELL API Number: 123-40958 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159584 Type: WELL API Number: 123-40959 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/17/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 21 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159585 Type: WELL API Number: 123-40960 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: Corrective Action: Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159587 Type: WELL API Number: 123-40962 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:  Date: **BradenHead**

Date of Last Brhd Test: 04/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 15 Fluid Type: None

End Surf Csg Pressure: --

Comment: Corrective Action: Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159588 Type: WELL API Number: 123-40963 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:  Date: **BradenHead**

Date of Last Brhd Test: 04/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: Corrective Action: Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159589 Type: WELL API Number: 123-40964 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 02/17/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 8 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159590 Type: WELL API Number: 123-40965 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301326 Type: WELL API Number: 123-29959 Status: SI Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: TA; Form 6A in well file.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 16 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**



Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, dry ground.</p> <p>On Tuesday, June 11, 2024 at approximately 1330, I, Inspector Brittani Santistevan, conducted an on-site inspection at CREAM 15N-B28HZ (Kerr McGee Oil &amp; Gas Onshore), at location ID: 302872 in WELD COUNTY, Colorado.</p> <p>While there, I observed mostly producing wellheads.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. It appears to be debris on multiple areas of location. Comply with Rule 606. (Corrective Action Date: June 25, 2024) See attached photo #3-6.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	06/11/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403821447	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582971">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582971</a>
714201127	Photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582963">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582963</a>