

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/17/2024

Submitted Date:

06/18/2024

Document Number:

705000727

FIELD INSPECTION FORM

Loc ID 319599 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243749	WELL	SI	06/01/2023	GW	123-11541	SCHEIDT-STATE 3-16 J	PA
319599	LOCATION	AC			-	SCHEIDT-STATE-61N67W 16CSE	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photo uploaded

Inspected Facilities

Facility ID: 243749 Type: WELL API Number: 123-11541 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 319599 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Scheidt State 3-16J); ECMC form 42 notice of start of plugging operations doc #403712101 received on 03/07/2024. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery are removed (AIP); ECMC flowline pre-abandonment notice doc #403642053 received 01/02/2024. No flowlines/ risers observed. Fenced excavation observed at facility/ battery area. Remediation work is in progress.	maclarej	06/18/2024
As outlined on COGCC form 19 spill report Doc #403820144 received on 06/11/2024: During facility decommissioning activities, historical impacts were discovered at the Scheidt State 3-16J separator flowline riser. The impacted soil will be removed and hauled for disposal. Lease operators are coached to conduct routine AVO inspections at all oil and gas locations.	maclarej	06/18/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000729	Fenced excavation at facility/ battery area	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591201