

Inspection Photos

06/14/2024

Operator: ANSCHUTZ EXPLORATION CORP
#3104

Location ID: 430926

Inspection Doc: 696205879

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provides an overview of the Location from south, southwest, northeast to north.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 3: Drone imagery. Photo provides an overview of the Location facing north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 4: Drone imagery. Photo provides an overview of the Location facing west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 5: Photo taken from the east end of the working pad surface, facing north and south. Interim reclamation of areas not reasonably needed for production has been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 6: Photos examples showing the slope drains installed on the southeast and northeast ends of the Location.

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 7: Photo left example of the slope drain outlets. Photo right shows sediment trap and toe of the fill slope.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



June 14, 2024

Photo 8: Erosion blankets implemented along cut slopes. Stormwater diversion ditch w/ rock checks implemented.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 9: Photo taken from the west end of the Location. Photo shows stained soils on the Location.

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 10: Photos taken from the west end of the Location. Photo shows fluids leaking from a loose cap at the methanol tank has resulted in a spill outside of containment. Operator on site tightened the valve to stop the leak.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 11: Photo shows improper disposal of potentially impacted materials- Operator on site indicated material to be diapers used during spill cleanup. Fluids observed spilling onto pad surface.



Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 12: Photos taken from the battery facility. Photo shows caps/plugs at lines were not replaced by trucker after pumping fluids.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 13: Continued from photo 12. Operator on site replaced caps at lines.