

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2024

Submitted Date:

06/18/2024

Document Number:

696205876

FIELD INSPECTION FORM

Loc ID 484545 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 3104
Name of Operator: ANSCHUTZ EXPLORATION CORP
Address: 555 17TH ST STE 2400
City: DENVER State: CO Zip: 80202

Findings:

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		<u>lindsey.organa@aec-denver.com</u>	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484545	LOCATION	AC			-	Coyote Fed 0397-14	RI
484991	WELL	AP	08/28/2023		081-07846	Coyote Fed 0397-14-3-1NH	RI
484992	WELL	AP	08/28/2023		081-07847	Coyote Fed 0397-14-2-4NH	RI
484993	WELL	AP	08/28/2023		081-07848	Coyote Fed 0397-14-2-3WNH	RI
484994	WELL	AP	08/28/2023		081-07849	Coyote Fed 0397-14-2-3NH	RI
484995	WELL	AP	08/28/2023		081-07850	Coyote Fed 0397-14-23-13NH	RI
484996	WELL	AP	08/28/2023		081-07851	Coyote Fed 0397-14-23-14NH	RI

General Comment:

On 6/14/2024, Reclamation Specialist Trujillo conducted a pre-drill stormwater and construction inspection at Anschutz Exploration Corp's Coyote Fed 0397-14 location in Moffat County, Colorado.

Location is Fee Surface, with Fed Minerals.

Location is within the following High Priority Habitats:

- Aquatic Sportfish Management Waters
- Greater Sage Grouse Priority Habitat Management Area
- Elk Severe Winter Range -Elk Winter Concentration Area
- Mule Deer Winter Concentration Area
- Pronghorn Winter Concentration

This is also a follow-up inspection Nos. 696205471 and 696205674 to document compliance for the following corrective actions:

- Signage Requirements
- Stormwater
- Protection of Soils

It was observed that corrective actions to address stormwater and topsoil protection compliance issues have been resolved; corrective actions to comply with 605 rules remain outstanding.

Refer to the "Location" and "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Topsoil		
Corrective Action:		Date:	
Type			
Comment:	Inspection #696205674 observed that signage at the Location entrance was missing the Oil and Gas Location name and Commission's assigned Oil and Gas Location identification number (ID #) pursuant to Rule 605.a.(1) and 605.a.(2); corrective action per Inspection #696205471 and remains applicable has not been addressed. It was observed in this inspection that the information pursuant to Rule 605.a.(1) and 605.a.(2) remains missing.		
Corrective Action:	Corrective action per Inspection #696205471: Comply with Rule 605.a	Date:	
Type	OTHER		
Comment:	Intersection of the lease road and public road		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location permit within tube at the Location entrance		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead signage posted at the Location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-888-696-1300 / 911

Corrective Action:

Date: _____

Good Housekeeping:

Type			
Comment:	Pipe/equipment stored on location have been taped/covered to prevent wildlife access.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 484545 CDP: _____

Comment:

Corrective Action: Date: _____

Form 2A COAs:

Comment:

Corrective Action: Date: _____

Wildlife BMPs:

Comment:

Corrective Action: Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
DITCHES	Yes		

Comments: Erosion BMPs: Perimeter of Location.

Other BMPs:

Corrective Action: _____ Date: _____

	Yes		
--	-----	--	--

Comments: Erosion BMPs: Slope drains x 2- SW/NW end of WPS. Inlet/outlet armored w/ rip-rap in conjunction with geotextile lining. Wood mulch erosion logs around armoring.

Other BMPs:

Corrective Action: _____ Date: _____

BERMS	Yes		
-------	-----	--	--

Comments: Erosion BMPs: WPS

Other BMPs:

Corrective Action: _____ Date: _____

	Yes		
--	-----	--	--

Comments: Erosion BMPs: Gravel / Compaction- WPS

Other BMPs:

Corrective Action: _____ Date: _____

DITCHES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: WPS

Other BMPs:

Corrective Action: _____ Date: _____

Yes

Comments: Erosion BMPs: Erosion Logs- straw wattles, perimeter of disturbance.
Filtrex w/ wood mulch at topsoil stockpiles. Inlets/outlets.

Other BMPs:

Corrective Action: Date:

Yes

Comments: Erosion BMPs: Erosion blankets implemented along sections of slopes.

Other BMPs:

Corrective Action: Date:

Comment: BMPs have been implemented at all points of discharge from the Location.
Stormwater and erosion control BMPs appeared to be in proper functioning condition at time of inspection. Stormwater corrective actions have been resolved.

Corrective Action: Date:

On Site Inspection (305):

Surface Owner Contact Information:

Name: Address:

Phone Number: Cell Phone:

Operator Rep. Contact Information:

Landman Name: Phone Number:

Date Onsite Request Received: Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name: Phone Number: Agreed to Attend:

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 484545 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484991 Type: WELL API Number: 081-07846 Status: AP Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484992 Type: WELL API Number: 081-07847 Status: AP Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484993 Type: WELL API Number: 081-07848 Status: AP Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484994 Type: WELL API Number: 081-07849 Status: AP Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484995 Type: WELL API Number: 081-07850 Status: AP Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484996 Type: WELL API Number: 081-07851 Status: AP Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS In Process

Comment [Straw mulch has been implemented at the topsoil stockpile in conjunction with erosion logs \(filtrex wood mulch\). 1002.c CAs have been addressed.](#)
[Ensure BMPs are maintained to protect the stockpiled soils pursuant to 1002.c.](#)

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696205877	sUAS Imagery and report	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591426
696205878	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591427