



FORM
INSP

Rev
X/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/13/2024
Submitted Date:
06/18/2024
Document Number:
705000720

Loc ID
323043

Inspector Name:
Maclaren, Joe

On-Site Inspection ☐
2A Doc Num: _____

Operator Information:
ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:
☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED
Findings:
4 Number of Comments
0 Number of Corrective Actions
☐ Corrective Action Response Requested
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244681	WELL	SI	10/01/2020	GW	123-12476	GLADYS SAWDEY 1	PA
412014	WELL	SI	10/01/2020	OW	123-30352	SAWDEY 6-30	PA
412016	WELL	SI	10/01/2020	OW	123-30354	SAWDEY 31-30	PA
412017	WELL	SI	01/01/2024	OW	123-30355	SAWDEY 21-30	SI
412018	WELL	SI	10/01/2020	OW	123-30356	SAWDEY 32-30	PA
412020	WELL	SI	01/01/2024	GW	123-30358	SAWDEY 22-30	SI

General Comment:
ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Date Run: 6/18/2024 Doc [#705000720]

Page 1 of 2

Inspected Facilities

Facility ID: 244681 Type: WELL API Number: 123-12476 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412014 Type: WELL API Number: 123-30352 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412016 Type: WELL API Number: 123-30354 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412017 Type: WELL API Number: 123-30355 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412018 Type: WELL API Number: 123-30356 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412020 Type: WELL API Number: 123-30358 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
(4) wells are plugged and abandoned; COGCC form 42 notices of start of plugging operations received February 2024. Associated flowline risers at PA wells are removed (WH OLF AIP in progress). Flowline risers at facility/ HHS areas OOSLAT. (2) wells SI wellheads OOSLAT. Fenced excavations observed at PA wells. Remediation work (historical) is in progress.	maclarej	06/18/2024
As outlined on COGCC form 19 spill report Doc #403817580 received on 06/10/2024: Historically impacted soil was discovered following cut and cap and wellhead flowline riser removal activities at the Sawdey Gladys 1 wellhead location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	06/18/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000730	Fenced excavation at PA well; signage	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591431
705000731	PA well; SI well to west	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591432