

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



**Location Overview: Location is within High Priority/Density  
Habitat areas. Location is approximately 22 yards from a  
drainage that contributes to the Colorado River.  
Section/Township/Range: 20 6S94W**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



**Photo # 2884 From inspection 708901973 conducted on 10/16/2023 Sediment migrating onto gravel track pad/BMP needs maintenance**



**Photo # 435 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



**Photo # 2885 From inspection 708901973 conducted on 10/16/2023 Sediment migrating onto gravel track pad/BMP needs maintenance**



**Photo # 436 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



**Photo # 2886 From inspection 708901973 conducted on 10/16/2023 Sediment migrating onto gravel track pad/BMP needs maintenance**



**Photo # 437 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



Oct 16, 2023 at 1:18:18 PM  
CO



Jun 11, 2024 at 11:30:56 AM  
CO

**Photo # 2887 From inspection 708901973 conducted on 10/16/2023 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Photo # 438 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



**Photo # 2889 From inspection 708901973 conducted on 10/16/2023 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Photo # 439 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



**Photo # 2890 From inspection 708901973 conducted on 10/16/2023 Sediment migrating onto gravel track pad/BMP needs maintenance**



**Photo # 440 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



**Photo # 2891 From inspection 708901973 conducted on 10/16/2023 Sediment migrating onto gravel track pad/BMP needs maintenance**



**Photo # 441 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



**Photo # 2892 From inspection 708901973 conducted on 10/16/2023 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Photo # 442 Sediment migrating onto gravel track pad/BMP needs maintenance**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad**  
**Location ID: 322444**



**Photo # 443 Sediment migrating onto gravel track pad/BMP needs maintenance**



**Photo # 444 Sediment migrating onto gravel track pad/BMP needs maintenance**