

Inspection Photos


Location: TEP Rocky Mountain LLC GV/33-22 frac pad

Location ID: 334730

Date: 6/18/2024



Entrance to location - Photo #02619



Location - Photo #02633

Inspection Photos

Location: TEP Rocky Mountain LLC GV/33-22 frac pad

Location ID: 334730

Date: 6/18/2024



Well heads - Photo #02620



Separators - Photo #02624

Inspection Photos


Location: TEP Rocky Mountain LLC GV/33-22 frac pad

Location ID: 334730

Date: 6/18/2024



ECD's - Photo #02627



Fire/Safety Hazard - Photo #02628

Inspection Photos

Location: TEP Rocky Mountain LLC GV/33-22 frac pad

Location ID: 334730

Date: 6/18/2024



Fire/Safety Hazzard - Photo #02630



Tank battery - Photo #02632

Inspection Photos

Location: TEP Rocky Mountain LLC GV/33-22 frac pad

Location ID: 334730

Date: 6/18/2024



Pump station - Photo #02645



Southwest corner of location - Photo #02652