

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2024

Submitted Date:

06/20/2024

Document Number:

696306431

FIELD INSPECTION FORMLoc ID 422173 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422149	WELL	TA	09/30/2019	GW	123-33170	Antelope 23-29	TA
422164	WELL	TA	09/30/2019	GW	123-33176	Antelope 13-29	TA
422170	WELL	TA	09/30/2019	GW	123-33178	Antelope 24-29	TA
422172	WELL	TA	10/07/2019	GW	123-33179	Antelope 14-29	TA
422179	WELL	TA	09/30/2019	OW	123-33181	Antelope I-29	TA
428126	WELL	TA	10/07/2019	OW	123-35238	Antelope H-29	TA
428136	WELL	TA	10/07/2019	OW	123-35244	Antelope M-29	TA

General Comment:

This is a Well PAD and Tank Battery Inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	All Wellhead Signs have faded no longer visible; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/19/2024
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at varies Wellheads and Separators		
Corrective Action:	Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.	Date:	07/19/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:	Heat Exhaust Stacks have been removed. Separators open to the Atmosphere need to be closed.		
Corrective Action:	Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.		Date: 07/19/2024
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Other	# 7		
Comment:	TA Wellheads		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLS	STEEL AST		40.368080,-104.351890
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 422149 Type: WELL API Number: 123-33170 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: [TA - Since 09.30.2019](#)

[MIT - 07.14.2021](#)

[Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File](#)

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422164 Type: WELL API Number: 123-33176 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: [TA - Since 09.30.2019](#)

[MIT - 07.14.2021](#)

[Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File](#)

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422170 Type: WELL API Number: 123-33178 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: [TA - Since 09.30.2019](#)

[MIT - 07.14.2021](#)

[Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File](#)

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422172 Type: WELL API Number: 123-33179 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: [TA - Since 10.07.2019](#)

[MIT - 07.14.2021](#)

[Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File](#)

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422179 Type: WELL API Number: 123-33181 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: [TA - Since 09.30.2019](#)

[MIT - 07.14.2021](#)

[Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File](#)

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 428126 Type: WELL API Number: 123-35238 Status: TA Insp. Status: TA

Idle Well

Purpose:

☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Since 10.07.2019
MIT - 07.15.2021
Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:

428136

Type:

WELL

API Number:

123-35244

Status:

TA

Insp. Status:

TA

Idle Well

Purpose:

☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Since 10.07.2019
MIT - 07.15.2021
Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Routine Field Inspection	petrie	06/20/2024
Unmarked Risers at varies Wellheads and Separators		
Separators open to Atmosphere		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306432	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6594831