

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/20/2024

Submitted Date:

06/20/2024

Document Number:

714201173

**FIELD INSPECTION FORM**

Loc ID: 424160 Inspector Name: Santistevan, Brittani On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424150	WELL	TA	05/06/2022	OW	123-33907	LOWER LATHAM PC G 02-22D	TA
424154	WELL	TA	05/06/2022	GW	123-33909	LOWER LATHAM PC G 01-32D	TA

**General Comment:**

THIS IS A WELLHEAD INSPCETION.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	unsued equipment inside wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	07/05/2024
Type	WEEDS		
Comment:	Overgrown vegetation inside wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	07/05/2024

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 424150 Type: WELL API Number: 123-33907 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A, 5A in well file.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 08/30/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 424154 Type: WELL API Number: 123-33909 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A, 5A in well file.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 08/30/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b>                      WEATHER CONDITIONS: sunny, dry ground.                      On Thursday, June 20, 2024 at approximately 1200, I, Inspector Brittani Santistevan, conducted an on-site inspection at LOWER LATHAM RESERVOIR CO PC G 2-22D, 1-32D (Noble Energy, Inc.), at location ID: 424160 in WELD COUNTY, Colorado.                      While there, I observed a temporarily abandoned wellhead.                      During this inspection the following possible compliance issues were observed:                      1. It appears to be overgrown vegetation inside the wellhead fencing. Comply with Rule 606. (Corrective Action Date: July 5, 2024) See attached photo #2, 4.                      2. It appears to be unused equipment inside wellhead fencing. Comply with Rule 606. (Corrective Action Date: July 5, 2024) See attached photo #5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	06/20/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201174	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595309">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595309</a>