

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2024

Submitted Date:

06/20/2024

Document Number:

694500682**FIELD INSPECTION FORM**Loc ID 442674 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
thomas, john	505-326-2659	jthomas@rlbayless.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442675	WELL	PA	06/05/2023	LO	081-07821	Foster State 1	EI
443258	SPILL OR RELEASE	CL	11/06/2017		-	SPILL/RELEASE POINT	EI

General Comment:

Environmental staff, Kris Neidel inspected the well pad. The following was observed; a plastic lined soil storage area on the northeast side of location, there was an approximate 20'x30' pile of soil (of varying height) in the storage area, the pad was being used for livestock watering with water tanks, some paneling on the ground with a well sign. Corrective Actions: the soil in the storage area shall be sampled for Table 915-1, The plastic liner shall be removed and disposed of offsite. Any corrective action(s) from previous inspections that have not been addressed are still applicable See attached See attached Photos.

Inspected Facilities									
Facility ID:	442675	Type:	WELL	API Number:	081-07821	Status:	PA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	443258	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Piles	Adequate		
Comment	a plastic lined soil storage area on the northeast side of location, there was an approximate 20'x30' pile of soil (of varying height) in the storage area			
Corrective Action	The soil in the storage area shall be sampled for Table 915-1, The plastic liner shall be removed and disposed of offsite. The plastic line can NOT be buried.			Date: 07/25/2024

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500683	photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595303