

Construction and Stormwater Inspection

Date: 06/18/2024

Operator: PDC ENERGY INC - 69175

Location ID: 485814

Inspection Document #: 708201335

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 1. Per Rule 406.c. a copy of the approved Form 2A was posted on location.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 2. Vehicle track out onto eastbound WCR 54.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 3. Vehicle track out onto westbound WCR 54.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 4. Taken near the locations access road; track out pad indicated by red arrow.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 5. Facing south along the access road, south of the construction area. It appears that topsoil has been salvaged from the new access road.



Photo 6. Southwest corner of the construction area.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 8. Facing northeast from the southern portion of the construction area. Cut and fill operations were ongoing at the time of this inspection.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 8. Taken from the southeast corner near the MLVT area. Perimeter stormwater control measures (ditch and berm) have been installed.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 9. Taken from the east side of the construction area, facing north. Photo illustrates perimeter stormwater control measures (ditch and berm) and the topsoil stockpile area.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 10. East side of construction area, facing north. Photo illustrates sediment trap that appears to be under construction.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 11. Eastside of construction area, facing north. Topsoil stockpile has been temporarily stabilized with equipment tracking, however, it has been installed parallel to grade. Long term stabilization techniques should be implemented (e.g. seeding).

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 12. Northwest side of topsoil stockpile; see comments in Photo 11.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 13. Southwest side of topsoil stockpile; see comments in Photo 11.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 14. Northeast corner of the construction area; photo illustrates perimeter stormwater control measures (ditch and berm) have been installed around the entire location and sediment trap with temporarily stabilized outlet protection.



Photo 15. Facing southeast from the northern portion of the construction area. Cut and fill operations were ongoing at the time of this inspection.



Photo 16. Northwest corner of the construction area; photo illustrates perimeter stormwater control measures (ditch and berm) have been installed around the entire location.

Inspection Photos
Location Name: Windom
Location ID: 485814



Photo 17. Facing southeast towards the future stormwater detention basin area, which is still being constructed at the time of this inspection.



Photo 18. Ditch and berm with a sediment trap located on the west side of the location.