

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2024

Submitted Date:

06/14/2024

Document Number:

696306415

**FIELD INSPECTION FORM**

Loc ID 435952 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435953	WELL	PR	09/01/2023	OW	123-38878	State Antelope D14-X44-2HNC	PR
435954	WELL	PR	09/01/2023	OW	123-38879	State Antelope 14-44-2HNC	PR
435955	WELL	PR	09/01/2023	OW	123-38880	State Antelope D-X-2HNC	PR
449330	WELL	PR	01/16/2019	OW	123-44262	State Antelope J24-2-14XRLNB	PR
449331	WELL	PR	02/06/2019	OW	123-44263	State Antelope 14-2-14XRLNB	PR
449332	WELL	PR	01/11/2019	OW	123-44264	State Antelope E-2-14XRLNB	PR
449333	WELL	PR	01/16/2019	OW	123-44265	State Antelope J14-2-14XRLNB	PR
454853	WELL	PR	03/01/2024	OW	123-46747	State Antelope 24-2-14XRLNB	PR

**General Comment:**

[This is a Follow-Up Inspection to FIR 696305468](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	South East Oil Tanks missing NFPA Labels. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/12/2024

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Riser has been marked		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	435953	Type:	WELL	API Number:	123-38878	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	435954	Type:	WELL	API Number:	123-38879	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	435955	Type:	WELL	API Number:	123-38880	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	449330	Type:	WELL	API Number:	123-44262	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	449331	Type:	WELL	API Number:	123-44263	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	449332	Type:	WELL	API Number:	123-44264	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	449333	Type:	WELL	API Number:	123-44265	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	454853	Type:	WELL	API Number:	123-46747	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

**Producing Well**

Comment:	PR	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. South East Oil Tanks missing NFPA Labels</a>	petrie	06/14/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403825962	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587769">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587769</a>
696306416	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587766">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587766</a>