

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2024

Submitted Date:

06/14/2024

Document Number:

713400130

FIELD INSPECTION FORMLoc ID 334542 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283345	WELL	PR	04/07/2014	GW	077-09026	MY WAY RANCH FED. 6-15	PR
283346	WELL	PR	03/31/2014	GW	077-09025	MY WAY RANCH FED. 6-14	PR
283347	WELL	PR	07/20/2015	GW	077-09024	MY WAY RANCH FED. 6-12	PR
283349	WELL	PR	06/24/2008	GW	077-09023	MY WAY RANCH FED. 6-7	PR
283352	WELL	PR	05/01/2020	GW	077-09022	MY WAY RANCH FED. 6-2	PR
283354	WELL	PR	06/24/2008	GW	077-09021	MY WAY RANCH FED. 6-10	PR
283356	WELL	PR	10/14/2015	GW	077-09020	MY WAY RANCH FED. 6-9	PR
283360	WELL	PR	10/14/2015	GW	077-09019	MY WAY RANCH FED. 6-8	PR
283362	WELL	PR	10/13/2015	GW	077-09018	MY WAY RANCH FED. 6-6	PR
283364	WELL	PR	02/22/2006	GW	077-09016	MY WAY RANCH FED. 6-11	PR

General Comment:

CECMC Inspection Report Summary

On 6/11/2024 at approximately 11:11, Compliance Inspector Dusty Popejoy conducted an on-site inspection at Laramie Energy LLC My Way Ranch Federal 6-11 Pad at Location ID #334542 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1) Tank battery - Multiple holes in containment liner, refer to photos with a CA date of 7/14/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location**Lease Road:**

Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	1-800-891-6191 or 911	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Vertical Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 10		

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	300 BBLs	STEEL AST		,	
Comment:	Multiple holes in containment liner, refer to photos					
	Telemetry on tanks					
Corrective Action:	Maintain and repair liner material to ensure spill or released materials will be maintained within the containment structure.				Date:	07/14/2024

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	283345	Type:	WELL	API Number: 077-09026 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283346	Type:	WELL	API Number: 077-09025 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283347	Type:	WELL	API Number: 077-09024 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283349	Type:	WELL	API Number: 077-09023 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283352	Type:	WELL	API Number: 077-09022 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283354	Type:	WELL	API Number: 077-09021 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283356	Type:	WELL	API Number: 077-09020 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283360	Type:	WELL	API Number: 077-09019 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	283362	Type:	WELL
API Number:	077-09018	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	283364	Type:	WELL
API Number:	077-09016	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts		Ditches				
Compaction		Culverts				
Berms		Compaction				
Rip Rap						
Ditches		Gravel				
Gravel		Culverts				
Sediment Traps						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403826146	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587948
713400131	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6587938