

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/30/2024

Submitted Date:

06/04/2024

Document Number:

694500667

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486848	TANK BATTERY	AC	05/31/2024		-	Overflow Tank	EI

General Comment:

ECMC staff Kris Neidel inspected this tank battery that consist of one AGT. Facility 486848, Weather was 60 degrees. ECMC staff was told by the previous operator that this tank was used as an overflow to the main tank battery secondary containment. No hydrocarbon staining was observed. No tank labels, signs or placard were observed. Corrective Actions: provide Sundry, Form 4 stating the purpose of the tank and intended use. The operator shall provide an evaluation of placarding the tank and secondary containment.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	No tank labels, signs or placards.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	No Emergency contact	
Corrective Action:		Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	1000 BBLS	STEEL AST		
Comment:	unsure of actual tank Capacity.				
Corrective Action:	provide Sundry, Form 4, stating the purpose of the tank and intended use. The operator shall provide an evaluation of placarding the tank and secondary containment.				Date: 06/19/2024

Paint

Condition	<input style="width: 800px;" type="text"/>
Other (Content)	<input style="width: 800px;" type="text"/>
Other (Capacity)	<input style="width: 800px;" type="text"/>
Other (Type)	<input style="width: 800px;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			
Comment:	The down gradient portion of containment is not bermed.			
Corrective Action:	provide Sundry, Form 4, stating the purpose of the tank and intended use. The operator shall provide an evaluation of placarding the tank and secondary containment.			Date: 06/19/2024

Venting:

Yes/No	<input style="width: 800px;" type="text"/>
Comment:	<input style="width: 800px;" type="text"/>
Corrective Action:	Date: _____

Flaring:

Type	<input style="width: 800px;" type="text"/>
Comment:	<input style="width: 800px;" type="text"/>

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 486848 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403813881	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573978
694500668	photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573974