



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Mechanical issue on wellhead needs to be fixed.		
Corrective Action:	Comply with rule 608.e	Date:	07/03/2024
Type	OTHER		
Comment:	Stained soil around wellhead needs to be removed.		
Corrective Action:	Comply with rule Rule 1002..(2).D	Date:	06/24/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	4' barb wire		
Corrective Action:		Date:	

**Equipment:**

Type:		#		corrective date
Bird Protectors		# 1		
Comment:				
Corrective Action:			Date:	
Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Vertical Heated Separator		# 1		
Comment:				
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:	Electric motor			
Corrective Action:			Date:	
Deadman # & Marked		# 4		
Comment:				
Corrective Action:			Date:	
Bradenhead		# 1		

Comment:	Plumbed to surface	Date:	
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:	Electric	Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	Date:	
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
------	--

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 204027 Type: WELL API Number: 005-06110 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/28/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On 6/18/24 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Peoria J Sand Unit 36                      Company Name- Tyler Rockies Exploration LTD                      API- 05-005-06110                      In Arapahoe County Colorado.                      While there, I observed PR well                      During this inspection the following possible compliance issues were observed:                      Contaminated soil near wellhead. Rule 1002..(2).D. 6/23/24                      Mechanical issue on wellhead. Rule 608.e. 7/3/24                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p>	medinaj	06/18/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505962	Inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6596352">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6596352</a>