

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 1119 From entrance to location




Photo # 1120 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 1121 Location



Photo # 1122 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Jun 21, 2024 at 1:53:55 PM
CO

Photo # 1123 Location



Jun 21, 2024 at 1:52:03 PM
CO

Photo # 1124 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 8201 From inspection 708903205 conducted on 03/05/2024 Barbed wire fence needs maintenance/barbed wire laying on ground/wildlife hazard



Photo # 1125 Barbed wire fence needs maintenance/barbed wire laying on ground/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 1126 Barbed wire fence needs maintenance/barbed wire laying on ground/wildlife hazard



Photo # 1127 Barbed wire fence needs maintenance/barbed wire laying on ground/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510




Photo # 8198 From inspection 708903205 conducted on 03/05/2024 Tank label losing adhesion & some required info is not visible



Photo # 1128 Tank label losing adhesion & some required info is not visible



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 2673 From inspection 708902787 conducted on 01/11/2024 PRV & rupture disc vent lines lack caps



Photo # 8199 From inspection 708903205 conducted on 03/05/2024 PRV & rupture disc vent lines lack caps

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 1129 PRV & rupture disc vent lines lack caps



Photo # 2674 From inspection 708902787 conducted on 01/11/2024 PRV & rupture disc vent lines lack caps

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 8200 From inspection 708903205 conducted on 03/05/2024 PRV & rupture disc vent lines lack caps



Photo # 1130 PRV & rupture disc vent lines lack caps