

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/19/2024

Submitted Date:

06/23/2024

Document Number:

693807374

FIELD INSPECTION FORMLoc ID 316245 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Taylor, Chad	(720) 788-6197	chad.taylor@state.co.us	Underground Injection Lead
,		COGCC.inspections@caerus oilandgas.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259449	WELL	SI	07/01/2022	DSPW	103-10098	PICEANCE CREEK UNIT T58X-8G	PA

General Comment:

Routine UIC Inspection.

Well plugged and abandoned 01/25/2024

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Type	Main			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign at location entrance			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	970-285-2615			
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	259449	Type:	WELL	API Number:	103-10098	Status:	SI	Insp. Status:	PA
Underground Injection Control									
UIC Violation:				Maximum Injection Pressure:					
UIC Routine									
Inj./Tube:	Pressure or inches of Hg			Previous Test Pressure			MPP		
	(e.g. 30 psig or -30" Hg)						Inj Zone:	WSTCA	
TC:	Pressure or inches of Hg			Previous Test Pressure			Last MIT:	07/16/2018	
Brhd:	Pressure or inches of Hg			Previous Test Pressure			AnnMTReq:		
Comment:		Well plugged and abandoned 01/25/2024							
Corrective Action:								Date:	
Method of Injection:									
Test Type:		Tbg psi:		Csg psi:		BH psi:			
Insp. Status:									
Comment:									
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807375	Inspection photos 6/19/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6597811