

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/19/2024

Submitted Date:

06/23/2024

Document Number:

693807380**FIELD INSPECTION FORM**Loc ID 316243 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Taylor, Chad	(720) 788-6197	chad.taylor@state.co.us	Underground Injection Lead
,		COGCC.inspections@caerus oilandgas.com	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259447	WELL	SI	07/01/2022	DSPW	103-10096	PICEANCE CREEK UNIT T86X-1G	SI

General Comment:[Routine UIC inspection.](#)

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	
Type	Main		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Sign at location entrance	
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Injection wellhead inside housing		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 259447

Type: WELL

API Number: 103-10096

Status: SI

Insp. Status: SI

Underground Injection Control

UIC Violation:

Maximum Injection Pressure:

UIC Routine

Inj./Tube:

Pressure or inches of Hg 559

Previous Test Pressure

MPP

(e.g. 30 psig or -30" Hg)

Inj Zone: WSTC

TC:

Pressure or inches of Hg 0

Previous Test Pressure

Last MIT: 04/09/2020

Brhd:

Pressure or inches of Hg 0

Previous Test Pressure

AnnMTReq:

Comment:

Routine UIC Inspection. Well shut in. No active injection at time of inspection.

Corrective Action:

Date:

Method of Injection: PUMP FEED

Test Type:

Tbg psi:

Csg psi:

BH psi:

Insp. Status:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Date Run: 6/23/2024 Doc [#693807380]

Page 4 of 5

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807381	Inspection photos 6/19/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6597814