

Construction and Stormwater Inspection

Date: 6/18/24

Operator: Crestone Peak Resources Operating LLC -
10633

Location ID: 486500

Inspection Document #: 713900705

Arapahoe County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: Lussing Trust 4-64
Location ID: 486500



Photo 1. The photo was taken at the entrance to the well location facing Southeast. The photo illustrates the location sign and Form 2A mailbox.



Photo 2. The photo was taken at the entrance to the well location facing East. The photo illustrates the sediment track out device, wind erosion BMP and concrete entrance.

Inspection Photos
Location Name: Lussing Trust 4-64
Location ID: 486500



Photo 3. The photo was taken at the entrance to the well location facing Southeast. The photo illustrates the temporary access has been reclaimed.



Photo 4. The photo was taken at the well location facing Northeast. The photo illustrates the sediment basin has been crimped and has an armored outlet/spillway per the stormwater plan.


Inspection Photos
Location Name: Lussing Trust 4-64
Location ID: 486500



Photo 5. The photo was taken at the well location facing Southwest. The photo illustrates the stormwater ditch around the South and West side of the location has been crimped and culverts have been armored with rip-rap and straw wattles.

Photo 6. The photo was taken at the well location facing Southeast. The photo illustrates interim areas and the topsoil stockpile have been straw crimped and seeded.

Note - Filtrex wattle has been installed around the East side of the stockpile, however there may be need for a BMP along the entirety of the stockpile.



Inspection Number: 713900705

Inspection Photos
Location Name: Lussing Trust 4-64
Location ID: 486500



Photo 7. The photo was taken at the well location facing Southwest. The photo illustrates no wildlife protection on surface casings.