

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2024

Submitted Date:

06/24/2024

Document Number:

713900702**FIELD INSPECTION FORM**Loc ID 320768 Inspector Name: Hansen, Logan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10646Name of Operator: AXIS EXPLORATION LLCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| , | | inspections@civiresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|-----------|--------------------|-------------|
| 204879 | WELL | PA | 06/28/2018 | GW | 005-06964 | UPRC 21X-21 | RI |
| 320768 | LOCATION | AC | | | - | UPRC-64S64W 21NENW | RI |
| 450974 | TANK BATTERY | AC | 06/04/2017 | | - | UPRC-64S64W 21NENW | RI |

General Comment:

This is a Final Reclamation Inspection for PA Well API#005-06964 and its associated tank battery in response to a Form 4 Final Reclamation Complete Notice. Well was plugged and abandoned 06/28/2018.

| | | | | | |
|--------------------------------------------------------|------|---------------------------------------------------------------------------------------------------------------------------------------|--|-------|-----------------|
| Location | | | | | |
| Overall Good: <input type="checkbox"/> | | | | | |
| Emergency Contact Number: | | | | | |
| Comment: | | | | | Date: _____ |
| Corrective Action: | | | | | |
| Overall Good: <input type="checkbox"/> | | | | | |
| Spills: | | | | | |
| Type | Area | Volume | | | |
| In Containment: No | | | | | |
| Comment: | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Equipment: | | | | | corrective date |
| Type: | | # | | | |
| Comment: | | No visual evidence of oil and gas equipment at the well or associated tank battery location. Refer to the attached inspection photos. | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|------------------------------------------------------------------------------------------|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 204879 | Type: | WELL | API Number: | 005-06964 | Status: | PA | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 320768 | Type: | LOCATION | API Number: | - | Status: | AC | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 450974 | Type: | TANK | API Number: | - | Status: | AC | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

| Environmental | | | |
|-------------------------------------------------------------------------------------------|------------------------------|-------------------------------|-------|
| Spills/Releases: | | | |
| Type of Spill: _____ | | Estimated Spill Volume: _____ | |
| Comment: <div>Remediation Project #11532 has been closed and approved on 8/29/2018.</div> | | | |
| Corrective Action: _____ | | Date: _____ | |
| Reportable: _____ | GPS: Lat _____ | Long _____ | |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____ | | |
| Water Well Complaint: | | | |
| | | Lat | Long |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : | _____ |
| Field Parameters: | | | |
| | | | |
| Sample Location: _____ | | Comment: _____ | |

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: [The well location \(Location ID 320768 with API 005-06964\) meets final reclamation regulations and standards due to the well and tank battery being superseded by a land use change to a homestead. The access road is now in use as the driveway to the house. Unable to find evidence of oil and gas activities and/or disturbances.](#)

Corrective Action: _____ Date _____

| | | | | | |
|---------------------------|------|---------------------------------|--------------------------|---------------------|--------------------------|
| Overall Final Reclamation | Pass | Well Release on Active Location | <input type="checkbox"/> | Multi-Well Location | <input type="checkbox"/> |
|---------------------------|------|---------------------------------|--------------------------|---------------------|--------------------------|

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| | | | | | | |

Comment:

At the time of this inspection, no stormwater erosion issues were observed at the location.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| | | |
|--------------|-------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Document Num | Description | URL |
| 713900704 | Inspection photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6599615 |