

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/02/2024

Submitted Date:

06/18/2024

Document Number:

699700386

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10442  
 Name of Operator: HUNTER RIDGE ENERGY SERVICES LLC  
 Address: 370 17TH STREET #1700  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Cholas, Nick		nick.cholas@state.co.us	
Arauzo, Steven		steven.arauza@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Pryor, Jason		Jason.Pryor@ovintiv.com	Ovintiv
Jackson, Ben		ben.jackson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446199	SPILL OR RELEASE	CL	06/16/2016		-	SPILL/RELEASE POINT 446199	EI
468839	SPILL OR RELEASE	CL			-	A27 12" poly line	EI
480369	SPILL OR RELEASE	CL			-	SPILL/RELEASE POINT	EI

**General Comment:**

ECMC Environmental Inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Trash and debris adjacent to the water treatment plant.		
Corrective Action:	Comply with Rule 606.	Date:	<u>07/02/2024</u>
Type	OTHER		
Comment:	Secondary containment surrounding the fuel tank adjacent to the water treatment plant is in disrepair.		
Corrective Action:	Install liner material to ensure spill or released materials will be maintained with containment structure.	Date:	<u>07/18/2024</u>
Type	DEBRIS		
Comment:	Trash and debris within East Stuart Gulch down gradient of the water treatment plant.		
Corrective Action:	Comply with Rule 606.	Date:	<u>07/02/2024</u>

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 446199 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 468839 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 480369 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: [See Remediation Project #9748 for more information.](#)  
 Personnel with CK Associates were present on location conducting an investigation on the springs and seeps in East Stuart Gulch. Hydrocarbon odors and sheens were observed by ECMC staff at multiple locations within East Stuart Gulch. See attached Photo Log for more information.

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403828250	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591009">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591009</a>
699700387	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591003">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6591003</a>