

Inspection Photos
Location: UPRR 42 PAN AM E 2 Flowline
Spill ID: 487060



Photo 1 –

Photo 2 –



Inspection Photos
Location
Facility ID:



Photo 3 – Stockpile w/ liner



Photo 4 – Stockpile w/ liner



Inspection Photos

Location

Facility ID:



Photo 5 –



Photo 6 – Stained soil within the excavation



Inspection Photos

Location

Facility ID:



Photo 7 – Stained soil within the excavation



Photo 8 – Release point



Inspection Photos
Location
Facility ID:



Photo 9 – Stained soil within the excavation.
Release point



Photo 10 – Wellhead signage



Inspection Photos

Location

Facility ID:




Photo 11 –

Photo 12 –



COLORADO
Energy & Carbon Manageme
Commission
Department of Natural Resources

Inspection Photos
Location
Facility ID:



Photo 13 –



Photo 14 –



Inspection Photos

Location

Facility ID:



Photo 15 –

