

Inspection Photos

Loc: 484357

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 6/24/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:484357 | Date: 6/24/2024

Inspection Photos



Photo 2. Facing east toward along the access road near the location. There are area where soils are very compacted. Seeding was performed in this area however vegetation will not grow well in compacted soils.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484357 | Date: 6/24/2024

Inspection Photos



Photo 3. Facing east toward the flowline disturbance. The vegetation is not establishing along the flowline and there are vehicle tracks which are causing unnecessary disturbance. The flowline must be reclaimed and stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484357 | Date: 6/24/2024

Inspection Photos



Photo 4. Facing west toward the flowline disturbance. There is an area of subsidence that needs to be filled in.



Inspection Photos



Photo 5. Facing north at the location. The vegetation has not yet established in the disturbed areas.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:484357 | Date: 6/24/2024

Inspection Photos



Photo 6. Facing southwest along the access road. There are vehicle tracks going off the road causing unnecessary disturbance.

