

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/25/2024

Submitted Date:

06/25/2024

Document Number:

716400227

FIELD INSPECTION FORM

Loc ID 317631 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------|---------------------------------|
| , | | rwatzman@kpk.com | All Inspections |
| , | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|-----------|----------------------|-------------|
| 239634 | WELL | SI | 11/01/2023 | GW | 123-07422 | SUCKLA FARMS C 2 | SI |
| 453906 | TANK BATTERY | AC | 01/31/2018 | | - | Suckla Farms battery | AC |

General Comment:

[This is a wellsite inspection](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | | |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | WEEDS | | |
| Comment: | dead vegetation over grown all along access road & wellsite. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 07/10/2024 |
| Type | OTHER | | |
| Comment: | stained soil by the WH. | | |
| Corrective Action: | Comply with rule 905.e | Date: | 07/10/2024 |

Overall Good:

Spills:

| Type | Area | Volume | |
|------|------|--------|--|
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|---|-------|--|
| Type | PUMP JACK | | |
| Comment: | fabricated round pipe | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Ancillary equip. has fabricated steel pipe and round stock. | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | Quantity | Comment | Corrective Action | Date |
|-------------|----------|-------------------------|-------------------|-----------------|
| Pump Jack | # 1 | | | corrective date |
| | | Comment: | | |
| | | Corrective Action: | | Date: |
| Bradenhead | # 1 | | | |
| | | Comment: | | |
| | | Corrective Action: | | Date: |
| Prime Mover | # 1 | | | |
| | | Comment: electric motor | | |
| | | Corrective Action: | | Date: |

| | | |
|---------------------------|--|-------|
| Type: Ancillary equipment | # 1 | |
| Comment: | electric panel, meter box and transformers | |
| Corrective Action: | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 239634 Type: WELL API Number: 123-07422 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/09/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: plumbed to surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453906 Type: TANK API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>ECMC Inspection Report Summary On Tuesday 6-25-2024 at approximately 1530 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: KP Kauffman Location name: Location ID #317631 Well Name: Suckla Farms C2 API # 05-123-07422 County: Weld Weather: Cloudy & hot Location: Dry While there, I observed a wellsite & tank battery, SI at the time of the inspection. During this inspection, I observed the following possible compliance issues: 606 Housekeeping: CA date 7-10-2024 905.e Housekeeping: 7-10-2024 See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p> | revasr | 06/25/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 716400228 | location | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6601138 |