

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/21/2024

Submitted Date:

06/25/2024

Document Number:

693807418

FIELD INSPECTION FORM

Loc ID 316814 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10453
Name of Operator: PARADOX UPSTREAM LLC
Address: 500 DALLAS ST SUITE #1650
City: HOUSTON State: TX Zip: 77002

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Taylor, Chad	(720) 788-6197	chad.taylor@state.co.us	Underground Injection Lead
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Nowak, Scott	713-899-0259	scottn@bogresources.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256810	WELL	TA	11/30/2022	DSPW	113-06072	ANDY'S MESA FEDERAL 15	TA

General Comment:

[Routine UIC inspection.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Type	Main		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	435-587-2237		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 256810 Type: WELL API Number: 113-06072 Status: TA Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____	MPP _____
	(e.g. 30 psig or -30" Hg)		Inj Zone: <u>CTRL</u>
TC:	Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____	Last MIT: <u>06/14/2022</u>
Brhd:	Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____	AnnMTReq: _____

Comment: Routine UIC Inspection. Well temporarily abandoned.

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807419	Inspection photos 6/21/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6601331