

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

OGCC RECEPTION

Receive Date:

01/22/2024

Document Number:

403623850

## Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

## Operator Information

OGCC Operator Number: 10633 Contact Person: James Miller  
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460  
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com  
City: DENVER State: CO Zip: 80202  
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes ☒ No ☐

## OFF LOCATION FLOWLINE

## FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 458018 Location Type: Production Facilities  
Name: MELBON RANCH 62N65W/17 NESE Number: 43-17  
County: WELD  
Qtr Qtr: NESE Section: 17 Township: 2N Range: 65W Meridian: 6  
Latitude: 40.134400 Longitude: -104.679300

## Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

## Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

## FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 458120 Flowline Type: Wellhead Line Action Type: Abandonment Verification

## OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 332025 Location Type: Well Site ☐  
Name: MELBON RANCH 62N65W/17 NESE Number: 43-17  
County: WELD No Location ID  
Qtr Qtr: NESE Section: 17 Township: 2N Range: 65W Meridian: 6  
Latitude: 40.136980 Longitude: -104.680090  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000  
Bedding Material: Native Materials Date Construction Completed: 05/06/2012  
Maximum Anticipated Operating Pressure (PSI):                      Testing PSI:                       
Test Date:                     

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 10/25/2023

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

Flowline was removed in its entirety via the open trench method. Once the flowline was removed, the trench was backfilled and the land surface was graded.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 458121 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 332025 Location Type: Well Site ☐  
Name: MELBON RANCH 62N65W/17 NESE Number: 43-17  
County: WELD No Location ID  
Qtr Qtr: NESE Section: 17 Township: 2N Range: 65W Meridian: 6  
Latitude: 40.136980 Longitude: -104.680090  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches)                       
Bedding Material: Native Materials Date Construction Completed: 03/11/2010  
Maximum Anticipated Operating Pressure (PSI):                      Testing PSI:                       
Test Date:

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 10/25/2023

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

Flowline was removed in its entirety via the open trench method. Once the flowline was removed, the trench was backfilled and the land surface was graded.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 462562 Flowline Type: Wellhead Line Action Type:

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 329865 Location Type: Well Site ☐

Name: MELBON RANCH 'E' UNIT-62N65W Number: 17SESE

County: WELD No Location ID

Qtr Qtr: SESE Section: 17 Township: 2N Range: 65W Meridian: 6

Latitude: 40.134108 Longitude: -104.682057

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000

Bedding Material: Native Materials Date Construction Completed: 04/08/1994

Maximum Anticipated Operating Pressure (PSI): Testing PSI:

Test Date:

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 01/04/2019

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

Flowline was disconnected from wellhead and from separator. Flowline was flushed with 25bbls fresh water prior to abandonment. Verified with LEL monitor that flowline was free of hydrocarbons. Flowline was plugged on both ends with 120lbs of slurry per State NTO.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 462433 Flowline Type: Wellhead Line Action Type:

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 332025 Location Type: Well Site ☐

Name: MELBON RANCH 62N65W/17 NESE Number: 43-17

County: WELD

No Location ID

Qtr Qtr: NESE Section: 17 Township: 2N Range: 65W Meridian: 6

Latitude: 40.136980 Longitude: -104.680090

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000

Bedding Material: Native Materials Date Construction Completed: 05/02/2012

Maximum Anticipated Operating Pressure (PSI): \_\_\_\_\_ Testing PSI: \_\_\_\_\_

Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 01/07/2019

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

Flowline was disconnected from the wellhead and the separator. Flowline was flushed with fresh water and flowline was removed from ground. Flowline was 100% removed.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 462432 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 332025 Location Type: Well Site ☐

Name: MELBON RANCH 62N65W/17 NESE Number: 43-17

County: WELD

No Location ID

Qtr Qtr: NESE Section: 17 Township: 2N Range: 65W Meridian: 6

Latitude: 40.136980 Longitude: -104.680090

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000

Bedding Material: Native Materials Date Construction Completed: 05/07/2012

Maximum Anticipated Operating Pressure (PSI): \_\_\_\_\_ Testing PSI: \_\_\_\_\_

Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 10/25/2023

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

Flowline was removed in its entirety via the open trench method. Once the flowline was removed, the trench was be backfilled and the land surface was graded.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 462430 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 332025 Location Type: Well Site ☐

Name: MELBON RANCH 62N65W/17 NESE Number: 43-17

County: WELD No Location ID

Qtr Qtr: NESE Section: 17 Township: 2N Range: 65W Meridian: 6

Latitude: 40.136980 Longitude: -104.680090

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000

Bedding Material: Native Materials Date Construction Completed: 04/28/2012

Maximum Anticipated Operating Pressure (PSI): Testing PSI:

Test Date:

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 10/25/2023

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

Flowline was removed in its entirety via the open trench method. Once the flowline was removed, the trench was backfilled and the land surface was graded.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 462431 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 332025 Location Type: Well Site ☐

Name: MELBON RANCH 62N65W/17 NESE

Number: 43-17

County: WELD

No Location ID

Qtr Qtr: NESE

Section: 17

Township: 2N

Range: 65W

Meridian: 6

Latitude: 40.136980

Longitude: -104.680090

Equipment at Start Point Riser: Well

### **Flowline Description and Testing**

Type of Fluid Transferred: Multiphase

Pipe Material: Carbon Steel

Max Outer Diameter:(Inches) 3.000

Bedding Material: Native Materials

Date Construction Completed: 05/08/2012

Maximum Anticipated Operating Pressure (PSI):

Testing PSI:

Test Date:

### **OFF LOCATION FLOWLINE Abandonment Verification**

Date: 10/25/2023

#### **Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

#### **Description of Abandonment Verification:**

Flowline was removed in its entirety via the open trench method. Once the flowline was removed, the trench was backfilled and the land surface was graded.

### **OPERATOR COMMENTS AND SUBMITTAL**

Comments

Form 44 filed to report POST-ABANDONMENT verification. The following flowline(s) were removed:

Flowline: serviced the Melbon Ranch 43-17 (05-123-21729)

Flowline: serviced the Melbon Ranch 33-17 (05-123-34583)

Flowline: serviced the Melbon Ranch 6-4-17 (05-123-34578)

Flowline: serviced the Melbon Ranch 8-8-17 (05-123-34580)

Flowline: serviced the Melbon Ranch 8-6-17 (05-123-34588)

Updated GIS data attached.

All other related flowlines will remain as previously reported.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed:

Date: 01/22/2024

Email: flowlines@civiresources.com

Print Name: Stephany Olsen

Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:

Director of COGCC

Date:

**Condtions of Approval**

| <u>COA Type</u> | <u>Description</u> |
|-----------------|--------------------|
|                 |                    |

**Attachment Check List**

| <u>Att Doc Num</u> | <u>Name</u>                   |
|--------------------|-------------------------------|
| 403629502          | OFF-LOCATION FLOWLINE GIS SHP |

Total Attach: 1 Files

**General Comments**

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|---------------------|
|                   |                | Stamp Upon Approval |

Total: 0 comment(s)