



**Location**

Overall Good:

**Signs/Marker:**

	Type BATTERY		
Comment:	PHOTO 5: NO CAPACITY OR NFPA STICKER POSTED @ TANK BATTERY.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/19/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			
In Containment: No					
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>					
<input type="checkbox"/> Multiple Spills and Releases?					

**Equipment:**

					corrective date
Type: Gas Meter Run	# 2				
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.				
Corrective Action:				Date:	
Type: Progressive Cavity	# 2				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 2				
Comment:					
Corrective Action:				Date:	
Type: Deadman # & Marked	# 6				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 4				
Comment:					
Corrective Action:				Date:	
Type: Vertical Separator	# 2				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 2				
Comment:	BOTH ARE ACCESSABLE				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		37.223070,-104.749540

Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:				
Corrective Action:				

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 266900 Type: WELL API Number: 071-07847 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 08/15/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 288634 Type: WELL API Number: 071-09143 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/27/2011 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403830426	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6594682">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6594682</a>
695109753	INSP. PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6594670">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6594670</a>