

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2024

Submitted Date:

06/20/2024

Document Number:

694500673**FIELD INSPECTION FORM**Loc ID 312847 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		htrujillo@rlbayless.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222579	WELL	PA	08/25/2008	DA	081-05649	KNOWLTON, B 15	EI

General Comment:

Environmental staff, Kris Neidel inspected the well pad. The Operators Environmental staff was on location collecting samples per REM #34336. The location of the wellhead was assumed to be at the tee post that was in the ground. The following was observed; 2 rig anchors were observed; one on the north east side and one on the north west side of the pad. The anchors were cables. There is a electrical subpanel (Disconnect) mounted on an electrical pole. At the Tee post/wellhead, there was; a pipe and a wire coming out of the ground. Corrective Actions: remove all equipment that was used for production, such as Electrical, piping and rig anchors. Any corrective action(s) from previous inspections that have not been addressed are still applicable See attached See attached Photos.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					corrective date
Type: Deadman # & Marked	# 2				
Comment:		2 rig anchors were observed; one on the north east side and one on the north west side of the pad.			
Corrective Action:		remove all equipment that was used for production			Date: 08/20/2024
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 222579 Type: WELL API Number: 081-05649 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403830997	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595312
694500674	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595299