

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2024

Submitted Date:

06/20/2024

Document Number:

694500682

**FIELD INSPECTION FORM**Loc ID 442674 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
thomas, john	505-326-2659	jthomas@rlbayless.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442675	WELL	PA	06/05/2023	LO	081-07821	Foster State 1	EI
443258	SPILL OR RELEASE	CL	11/06/2017		-	SPILL/RELEASE POINT	EI

**General Comment:**

Environmental staff, Kris Neidel inspected the well pad. The following was observed; a plastic lined soil storage area on the northeast side of location, there was an approximate 20'x30' pile of soil (of varying height) in the storage area, the pad was being used for livestock watering with water tanks, some paneling on the ground with a well sign. Corrective Actions: the soil in the storage area shall be sampled for Table 915-1, The plastic liner shall be removed and disposed of offsite. Any corrective action(s) from previous inspections that have not been addressed are still applicable See attached See attached Photos.

Inspected Facilities									
Facility ID:	442675	Type:	WELL	API Number:	081-07821	Status:	PA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	443258	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Piles	Adequate		
Comment	a plastic lined soil storage area on the northeast side of location, there was an approximate 20'x30' pile of soil (of varying height) in the storage area			
Corrective Action	The soil in the storage area shall be sampled for Table 915-1, The plastic liner shall be removed and disposed of offsite. The plastic line can NOT be buried.			Date: 07/25/2024

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403830999	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595314">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595314</a>
694500683	photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595303">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595303</a>