

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2024

Submitted Date:

06/18/2024

Document Number:

696306429**FIELD INSPECTION FORM**Loc ID 422161 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422150	WELL	TA	09/20/2019	GW	123-33171	Antelope 11-29	TA
422159	WELL	TA	09/24/2019	GW	123-33173	Antelope 22-29	TA
422162	WELL	TA	09/24/2019	GW	123-33174	Antelope 12-29	TA
422163	WELL	TA	08/05/2019	GW	123-33175	Antelope 21-29	TA
422177	WELL	TA	09/23/2019	GW	123-33180	Antelope G-29	TA
428130	WELL	TA	08/05/2019	OW	123-35240	Antelope L-29	TA
428131	WELL	TA	09/19/2019	OW	123-35241	Antelope F-29	TA

General Comment:

This is a Well PAD and Tank Battery Inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Tumbleweed Debris at Separators and Wellheads; see photos		
Corrective Action:	Comply with Rule 606	Date:	07/19/2024
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at Varies Wellheads and Separators; see photos		
Corrective Action:	Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.	Date:	07/19/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:	Heat Exhaust Stacks have been removed. Separators open to Atmosphere need to be closed.		
Corrective Action:	Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.		Date: 07/19/2024
Type: Other	# 7		
Comment:	TA Wellheads		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLS	STEEL AST		40.373900,-104.353700
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 422150 Type: WELL API Number: 123-33171 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 09.20.2019

MIT - 06.14.2021

Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422159 Type: WELL API Number: 123-33173 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 09.24.2019

MIT - 06.14.2021

Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422162 Type: WELL API Number: 123-33174 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 02.04.2019

MIT - 06.14.2021

Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422163 Type: WELL API Number: 123-33175 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 08.05.2019

MIT - 04.22.2021

Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422177 Type: WELL API Number: 123-33180 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Since 09.23.2019

MIT - 06.14.2021

Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 428130 Type: WELL API Number: 123-35240 Status: TA Insp. Status: TA

Idle Well

Purpose:

☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Since 08.15.2019
MIT - 04.22.2021
Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:

428131

Type:

WELL

API Number:

123-35241

Status:

TA

Insp. Status:

TA

Idle Well

Purpose:

☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment:

TA - Since 08.05.2019
MIT - 04.22.2021
Form 6A - 403213997 with a Plug Due Date of 12.31.2029 is on File

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Routine Field Inspection.	petrie	06/18/2024
* Tumbleweed Debris at Separators and Wellheads		
* Unmarked Risers at Separators and Wellheads		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403830572	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6594832
696306430	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6594830